00862.022476



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
Yoshikazu MIYAJIMA et al.	;	Examiner: R. E. Fuller
Application No.: 10/022,506	;	Group Art Unit: 2851
Filed: December 20, 2001	;	
For: EXPOSURE APPARATUS, DEVICE MANUFACTURING METHOD, SEMICONDUCTOR MANUFACTURING FACTORY, AND EXPOSURE APPARATUS MAINTENANCE METHOD U.S. Patent No. 6,791,670 B2	; ; ; ;	October 26, 2004
Issued: September 14, 2004	:	Certificate 0CT 2 9 2004
Commissioner for Patents P.O. Box 1450		of Correction

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

Patentees request that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes and mistakes of a minor nature which are not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed. 10/27/2004 NNGUYEN2 00000090 6791670

-1-

100.00 OP 01 FC:1811

Alexandria, VA 22313-1450

Attention: Certificate of Correction Branch

Account No. 06-1205. A duplicate of this paper is enclosed for that purpose.

Patentees' undersigned attorney may be reached in our Washington, D.C. Office by telephone at (202) 530-1010. All correspondence should continue to be directed to our below-listed address.

Respectfully submitted,

Attorney for Patentees

Steven E. Warner

Registration No. 33,326

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

SEW/eab

SE W/Cau

DC_MAIN 182214v1

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.: 6,791,670 B2

DATED : September 14, 2004

INVENTOR(S): Yoshikazu MIYAJIMA et al. Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE COVER PAGE:

In item "(56) References Cited," under "FOREIGN PATENT DOCUMENTS," the first-listed document "JP 10-309071 11/1988" should read -- JP 10-309071 11/1998 -and the fifth-listed document "JP 2000209838 A * 7/2000" should read -- JP 2000-209838 A * 7/2000 --.

In item "(57) ABSTRACT," line 4, "multi-layer" should read -- multi-layered --.

COLUMN 1:

Line 53, "portion 1," should read -- portion I, --.

COLUMN 6:

Line 13, "FIG. 29A, should read -- FIG. 29A; --.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>6,791,670 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.: 6,791,670 B2

DATED : September 14, 2004

Page 2 of 3 INVENTOR(S): Yoshikazu MIYAJIMA et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7:

Line 39, "comer" should read -- corner --. Line 40, "comer" should read -- corner --.

COLUMN 8:

Line 8, "Fine" should read -- fine --.

COLUMN 11:

Line 34, "allow" should read -- alloy --.

Line 47, "a" should read -- α --.

Line 55, "in" should read -- ¶ Alternatively, in --.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,791,670 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)



UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.: 6,791,670 B2

: September 14, 2004 DATED

INVENTOR(S): Yoshikazu MIYAJIMA et al.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 12:

Line 2, "acopper-" should read -- a copper- --.

Line 3, "allow" should read -- alloy --.

Line 34, "cooper" should read -- copper --.

COLUMN 14:

Line 3, "A" should read -- a --.

Line 65, "(TCP/TP)" should read -- (TCP/IP) --.

COLUMN 16:

Line 4, "he" should read -- be --.

COLUMN 18:

Line 11, "not" should read -- not limited to --.

Line 26, "ate" should read -- are --.

Line 58, "filly" should read -- fully --.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>6,791,670 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)

00862.022476 PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
Yoshikazu MIYAJIMA et al.	:)	Examiner: R. E. Fuller
Application No.: 10/022,506	:	Group Art Unit: 2851
Filed: December 20, 2001	:)	
For: EXPOSURE APPARATUS, DEVICE MANUFACTURING METHOD, SEMICONDUCTOR MANUFACTURING FACTORY, AND EXPOSURE	:) :)	October 26, 2004
APPARATUS MAINTENANCE METHOD	:	
U.S. Patent No. 6,791,670 B2) :	
Issued: September 14, 2004)	

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Attention: Certificate of Correction Branch

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

Patentees request that a Certificate of Correction be issued by the Patent and

Trademark Office due to errors which appear in the printed patent as a result of Patent and

Trademark Office mistakes and mistakes of a minor nature which are not the fault of the Patent

and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Account No. 06-1205. A duplicate of this paper is enclosed for that purpose.

Patentees' undersigned attorney may be reached in our Washington, D.C. Office by telephone at (202) 530-1010. All correspondence should continue to be directed to our below-listed address.

Respectfully submitted,

Attorney for Patentees Steven E. Warner

Registration No. 33,326

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

SEW/eab

DC_MAIN 182214v1

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.: 6,791,670 B2

DATED : September 14, 2004

INVENTOR(S): Yoshikazu MIYAJIMA et al. Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE COVER PAGE:

In item "(56) References Cited," under "FOREIGN PATENT DOCUMENTS," the first-listed document "JP 10-309071 11/1988" should read -- JP 10-309071 11/1998 -and the fifth-listed document "JP 2000209838 A * 7/2000" should read -- JP 2000-209838 A * 7/2000 --.

In item "(57) ABSTRACT," line 4, "multi-layer" should read -- multi-layered --.

COLUMN 1:

Line 53, "portion 1," should read -- portion I, --.

COLUMN 6:

Line 13, "FIG. 29A, should read -- FIG. 29A; --.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,791,670 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)



PRINTER'S TRIM LINE Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.: 6,791,670 B2

DATED : September 14, 2004

INVENTOR(S): Yoshikazu MIYAJIMA et al. Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7:

Line 39, "comer" should read -- corner --. Line 40, "comer" should read -- corner --.

COLUMN 8:

Line 8, "Fine" should read -- fine --.

COLUMN 11:

Line 34, "allow" should read -- alloy --.

Line 47, "a" should read -- α --.

Line 55, "in" should read -- ¶ Alternatively, in --.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>6,791,670 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)



UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.: 6,791,670 B2

: September 14, 2004 **DATED**

INVENTOR(S): Yoshikazu MIYAJIMA et al. Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 12:

Line 2, "acopper-" should read -- a copper- --.

Line 3, "allow" should read -- alloy --.

Line 34, "cooper" should read -- copper --.

COLUMN 14:

Line 3, "A" should read -- a --.

Line 65, "(TCP/TP)" should read -- (TCP/IP) --.

COLUMN 16:

Line 4, "he" should read -- be --.

COLUMN 18:

Line 11, "not" should read -- not limited to --.

Line 26, "ate" should read -- are --.

Line 58, "filly" should read -- fully --.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,791,670 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)

